

Date:

Hamel Chevrolet Buick GMC

9455, Lacordaire Saint-Leonard H1R 3E8

1 581 703-8313

| Make / Model | |
|----------------------------|-----------------------------|
| Gmc Canyon AT4 * Sièges en | |
| Year | Mileage indicated / actual* |
| 2021 | 87,801 km |
| Transmission | Drive Type |
| automatic | 4x4 |
| Engine | Fuel Type |
| 6 cyl. / 3.6 liters | |
| Serial number | Stock number |
| | H4691 |



EQUIPMENTS

SALE PRICE

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power driver seat, Power steering, Power windows, Remote starter, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Two-toned paint, Satellite radio, Bucket seats, Reverse camera, Climate control, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Antitheft system, Front reading lamps, Keyless entry, Audio steering controls

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

| | Category | |
|--|---|--|
| Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: | As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: | |
| | A 6 months or B 3 months or C 1 month or 10 000 km B 5 000 km C | |
| | D Good working E No Warranty | |
| Repairs done and mechanical verification certificate Comments | | |
| The following repairs have been done on this vehicle since the | ne dealer's possession. | |
| If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code. | | |
| Optional repairs | | |
| The following defects have been noted on this vehicle and can be repaired at the cost mentioned below : | | |
| | | |

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #: 8530411